

(AF64-4361)



Important!

Aeroflow's billet aluminium timing cover is a two piece cover. When installing the timing cover (and anytime the 2 pieces have been separated) the two pieces must have a gasket sealer applied to the mating surfaces. Failure to do so will likely result in engine oil and/or vacuum leaks.



Important!

Aeroflow's billet aluminium timing cover is a two piece cover. When installing the timing cover (and anytime the 2 pieces have been separated) the two pieces must have a gasket sealer applied to the mating surfaces. Failure to do so will likely result in engine oil and/or vacuum leaks.



Important!

Aeroflow's billet aluminium timing cover is a two piece cover. When installing the timing cover (and anytime the 2 pieces have been separated) the two pieces must have a gasket sealer applied to the mating surfaces. Failure to do so will likely result in engine oil and/or vacuum leaks.